

Message

**From:** Grant J Ovist [grant.ovist@gm.com]  
**Sent:** 5/25/2017 7:23:13 PM  
**To:** Kim, Seongyup@ARB [Seongyup.Kim@arb.ca.gov]  
**CC:** Robert J. Vito [robert.j.vito@gm.com]; Igor Anilovich [igor.anilovich@gm.com]; Doug DeVries [doug.devries@gm.com]; Nguyen, Duc@ARB [Duc.Nguyen@arb.ca.gov]; Wright, DavidA [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=4f14a47c701547479b12bee35117d0a9-Wright, David A.]  
**Subject:** RE: Questions to JGMXJ01.6356 (diesel Cruze, Equinox, Terrain) AECD  
**Attachments:** GM 2018MY Diesel LH7 JGMXJ01 6356 AECD review 5\_18\_2017-20120525 (TC).pdf

Hello Seongyup,

The attached PDF contains answers to questions received on 5/18.  
Please let us know if you have any further questions regarding JGMXJ01.6356

Thank you,

Grant Ovist  
GM In-Use Emissions Compliance  
Auxiliary Emission Control Device Engineer  
VOICES Representative – Emission Certification and Compliance  
[grant.ovist@gm.com](mailto:grant.ovist@gm.com)  
+1.586.709.2689



---

**From:** Kim, Seongyup@ARB [mailto:Seongyup.Kim@arb.ca.gov]  
**Sent:** Thursday, May 18, 2017 10:46 AM  
**To:** Grant J Ovist <grant.ovist@gm.com>  
**Cc:** Robert J. Vito <robert.j.vito@gm.com>; Igor Anilovich <igor.anilovich@gm.com>; Doug DeVries <doug.devries@gm.com>; Nguyen, Duc@ARB <Duc.Nguyen@arb.ca.gov>; David A. Wright (wright.davida@epa.gov) (wright.davida@epa.gov) <wright.davida@epa.gov>  
**Subject:** [EXTERNAL] Questions to JGMXJ01.6356 (diesel Cruze, Equinox, Terrain) AECD

Hi Grant,

We would like to understand the difference between 2017 AECD and 2018 AECD. Like GM did for 2018 6.6L and 2.8L AECD, please provide the list of change.

Regarding EGR being not used on the torque curve below **CBI / Ex. 4** in section 3. EGR system control and modifiers, we would like to know in-use frequency of vehicle in the area of **CBI / Ex. 4** as you indicated in torque curve on 4/24/2017 response. We think it could be expressed by showing gear shift points on the torque curve. If you have a different or better way of responding in-use frequency, please suggest.

One of the reasons for shutting off EGR below **CBI / Ex. 4** in high load is engine is operating very close to the turbocharger compressor surge line. Please provide backup data to support the reason.

If you have any questions on this, please let me know.

Thanks,  
Seongyup

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.